

Tolerance a úchytky kalibrů

Stupeň přesnosti	Označení	Rozsah v mm													Úchytky geometr. tvaru
		do 3	nad 3 do 6	nad 6 do 10	nad 10 do 18	nad 18 do 30	nad 30 do 50	nad 50 do 80	nad 80 do 120	nad 120 do 180	nad 180 do 250	nad 250 do 315	nad 315 do 400	nad 400 do 500	
		μm													
6	z, z ₁	1	1,5	1,5	2	2	2,5	2,5	3	4	5	6	7	8	IT 1 IT 2 IT 1
	y, y ₁	1	1	1	1,5	1,5	2	2	3	3	4	5	6	7	
	α, α ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	z ₁	1,5	2	2	2,5	3	3,5	4	5	6	7	8	10	11	
	y ₁	1,5	1,5	1,5	2	3	3	3	4	4	5	6	6	7	
	H, H ₁ *)	1,2	1,5	1,5	2	2,5	2,5	3	4	5	7	8	9	10	
	H ₁ , H _p	2	2,5	2,5	3	4	4	5	6	8	10	12	13	15	
7	z, z ₁	1,5	2	2	2,5	3	3,5	4	5	6	7	8	10	11	IT 2 IT 1 IT 1
	y, y ₁	1,5	1,5	1,5	2	3	3	3	4	4	6	7	8	9	
	α, α ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	H, H ₁	2	2,5	2,5	3	4	4	5	6	7	10	12	13	15	
	H ₁	—	—	1,5	2	2,5	2,5	3	4	5	7	8	9	10	
	H ₁ *)	—	—	—	—	—	—	—	—	—	—	—	—	—	
	H _p	0,8	1	1	1,2	1,5	1,5	2	2,5	3,5	4,5	6	7	8	
8	z, z ₁	2	3	3	4	5	6	7	8	9	12	14	16	18	IT 2 IT 3 IT 1
	y, y ₁	3	3	3	4	4	5	5	6	6	7	9	9	11	
	α, α ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	H	2	2,5	2,5	3	4	4	5	6	8	10	12	13	15	
	H ₁	3	4	4	5	6	7	8	10	12	14	16	18	20	
	H ₁ *)	—	—	—	—	—	—	—	—	—	—	—	—	—	
	H _p	1,2	1,5	1,5	2	2,5	2,5	3	4	5	7	8	9	10	
9	z, z ₁	5	6	7	8	9	11	13	15	18	21	24	28	32	IT 2 IT 3 IT 1
	y, y ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	α, α ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	H	2	2,5	2,5	3	4	4	5	6	8	10	12	13	15	
	H ₁	3	4	4	5	6	7	8	10	12	14	16	18	20	
	H ₁ *)	—	—	—	—	—	—	—	—	—	—	—	—	—	
	H _p	1,2	1,5	1,5	2	2,5	2,5	3	4	5	7	8	9	10	

Pokračování

Pokračování

Stupeň přesnosti	Označení	Rozsah v mm													Úchytky geometr. tvaru
		do 3	nad 3 do 6	nad 6 do 10	nad 10 do 18	nad 18 do 30	nad 30 do 50	nad 50 do 80	nad 80 do 120	nad 120 do 180	nad 180 do 250	nad 250 do 315	nad 315 do 400	nad 400 do 500	
		μm													
10	z, z ₁	5	6	7	8	9	11	13	15	18	24	27	32	37	IT 2 IT 3 IT 1
	y, y ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	α, α ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	H	2	2,5	2,5	3	4	4	5	6	8	10	12	13	15	
	H ₁	3	4	4	5	6	7	8	10	12	14	16	18	20	
	H ₁ *)	—	—	—	—	—	—	—	—	—	—	—	—	—	
	H _p	1,2	1,5	1,5	2	2,5	2,5	3	4	5	7	8	9	10	
11	z, z ₁	10	12	14	16	19	22	25	28	32	40	45	50	55	IT 4 IT 3 IT 1
	y, y ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	α, α ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	H, H ₁	4	5	6	8	9	11	13	15	18	20	23	25	27	
	H ₁	—	—	4	5	6	7	8	10	12	14	16	18	20	
	H ₁ *)	—	—	—	—	—	—	—	—	—	—	—	—	—	
	H _p	1,2	1,5	1,5	2	2,5	2,5	3	4	5	7	8	9	10	
12	z, z ₁	10	12	14	16	19	22	25	28	32	45	50	65	70	IT 4 IT 3 IT 1
	y, y ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	α, α ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	H, H ₁	4	5	6	8	9	11	13	15	18	20	23	25	27	
	H ₁	—	—	4	5	6	7	8	10	12	14	16	18	20	
	H ₁ *)	—	—	—	—	—	—	—	—	—	—	—	—	—	
	H _p	1,2	1,5	1,5	2	2,5	2,5	3	4	5	7	8	9	10	
13	z, z ₁	20	24	28	32	36	42	48	54	60	80	90	100	110	IT 5 IT 5 IT 2
	y, y ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	α, α ₁	0	0	0	0	0	0	0	0	0	0	0	0	0	
	H, H ₁	10	12	15	18	21	25	30	35	40	46	52	57	63	
	H ₁	—	—	9	11	13	16	19	22	25	29	32	36	40	
	H ₁ *)	—	—	—	—	—	—	—	—	—	—	—	—	—	
	H _p	2	2,5	2,5	3	4	4	5	6	8	10	12	13	15	

Pokračování